

Date: 19/09/03

Subject: Mounting – New Style Tram Lockout Valve.

Unit/Part Affected: CP47505-009 Tram Lockout Valve.

As stated in bulletin SB03-007 the manufacturer made some changes to this valve. It now uses different port numbers for the pressure hose as well as a different method of mounting.

To further elaborate on the mounting changes please refer to the information below:

The simplest method of mounting the new valve is to drill and tap a new hole in the existing mounting plate so the center distance becomes 2.5" to accept the new valve body.

