

CUBEX LTD. PRODUCT UPDATE

BULLETIN: PU-0001

DATE: OCTOBER 11, 1989

SUBJECT: DUMP CYLINDERS LEAKING DOWN

INFORMATION: Load checks have been added to all new drills to remedy this problem and it is advised that this change be implemented on all existing drills also. The part # for the load check valve is CP47573 and should be connected as illustrated.

For further information contact your local Cubex Ltd. Representative.

